

# Oil Field Environmental Incident Summary

**Incident:** 20140102163536

**Date/Time of Notice:** 01/02/2014 16:26

**Responsible Party:** Oasis

**Well Operator:** OASIS PETROLEUM NORTH AMERICA LLC

**Well Name:** MANTLE 1-21H

**Field Name:** FOREMAN BUTTE

**Well File #:** 15584

**Date Incident:** 1/2/2014

**Time Incident:** 14:00

**Facility ID Number:**

**County:** MCKENZIE

**Twp:** 150

**Rng:** 102

**Sec:** 21

**Qtr:**

**Location Description:** Bulkhead on salt water tank leaked. All contained in dike.

**Submitted By:** John M. Jochim

**Received By:**

**Contact Person:** John M. Jochim  
1001 FANNIN STE 1500  
HOUSTON, TX 77002

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 2 Miles

**Distance Nearest Water Well:** 1 Miles

**Type of Incident:** Tank Leak

**Release Contained in Dike:** Yes - Within Dike

**Reported to NRC:** Unknown

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	0	barrels	0	barrels		
<b>Brine</b>	7	barrels	7	barrels		
<b>Other</b>	0	barrels	0	barrels		

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

**Areal Extent:**

***Potential Environmental Impacts:***

***Action Taken or Planned:***

Sucked up brine.

***Wastes Disposal Location:*** In salt water tank.

***Agencies Involved:***

***Updates***

---

***Date:*** 1/3/2014      ***Status:*** Reviewed - Assigned to Other Agency      ***Author:*** Stockdill, Scott

***Updated Oil Volume:***

***Updated Salt Water Volume:***

***Updated Other Volume:***

***Updated Other Contaminant***

***Notes:***

According to the incident summary report, this spill remained within the dikes on location. NDIC retains oversight.